



NO SCALE

NOTES:

1. ALL BOLTS BELOW GRADE ON FIRE HYDRANT SHALL BE STAINLESS STEEL.
  2. ALL BOLTS ON AUXILIARY VALVE SEAL PLATE AND BONNET SHALL BE STAINLESS STEEL.
  3. THRUST BLOCKING SHALL BE CONSTRUCTED SO HYDRANT DRAIN HOLE IS NOT OBSTRUCTED.
  4. HYDRANT SHALL BE PAINTED RED.
- EJIW PART #00982020
5. ALL MATERIAL MUST BE "MADE IN USA".

VILLAGE OF NEW LENOX  
STANDARD DETAIL  
FOR  
FIRE HYDRANT

REV:	6
DATE:	AUGUST 2014
FILE:	WATER\FRHYDET